

















Part List

- A**  x1
- B**  x1
- C**  x1
- D**  x1
- E**  x1
- F**  x1
- G**  M10X60MM x2
- H**  M10 x1
- I**  M10 x1
- J**  x1
- K**  x1
- Q**  x1
- R**  x1
- S**  x6


Step 1



Step 2



Step 3



Step 4

